

US EPA ARCHIVE DOCUMENT

<b>UNIT LOG</b>	1. Incident Name Kalamazoo River/Enbridge Oil Spill	2. Date Prepared 05/26/2012	3. Time Prepared 1600
4. Unit Name/Designators Situation Unit	5. Unit Leader (Name and Position) Melinda Luetke, Planning Section Chief		6. Operational Period 0700, 05/17/12 – 0700, 05/31/12
7. Personnel Roster Assigned			
Name		ICS Position	Home Base
Larry Rader		Situation Unit Leader	Chicago, Illinois
8. Activity Log			
Time	Major Events		
09:00	<p>Overflight Operational status:</p> <ul style="list-style-type: none"> <li>• Source area pond, no sheen observed.</li> <li>• Frac-Tank City decon pad. No activity observed.</li> <li>• Confluence, no sheen observed.</li> <li>• Saylor's Landing, no public activity observed.</li> <li>• MP4.5 LDB, Former Lily Pad area, no sheen observed.</li> <li>• Ceresco Dam, no sheen observed.</li> <li>• MP 10.75 sediment trap, sheen observed within containment.</li> <li>• MP 14.98 island, containment around island was removed last week, no sheen observed.</li> <li>• Control point at Battle Creek spillway. No sheen observed.</li> <li>• Rock Tenn inlet, no activity observed.</li> <li>• MP 10.25 sediment trap. Sediment sampling device was observed to be out of water.</li> <li>• MP 30.8 LDB containment. Sheen observed within containment. Operations crew notified to conduct inspection.</li> <li>• E4.0 control point. Debris observed within containment. No sheen observed.</li> <li>• Morrow Lake Delta, looking east. No sheen observed in delta.</li> <li>• Sheen observed along shoreline in northern cove on Morrow Lake near MP38.25. Operations crew notified to conduct inspection.</li> <li>• Morrow Lake Dam, no sheen or activity observed.</li> <li>• South bank of river below Morrow Lake Dam. No sheen observed.</li> </ul>		
	Additional observations: None		
15:00	Return to ICP.		
9. Prepared by (Name and Position) Larry Rader, Situation Unit Leader, USEPA-START			